ASM Manager 1.5.12 release notes

Fixes

1. Bank-to-bank internal transfers duplicate patches, overwrite other patches
2. HS Factory Wipeout + Restore Banks do not replace Banks F-H
3. Updated USB driver for Windows
4. New minimum system requirements for Windows computers:

   Windows 10+ (build 1709 or higher).

   Note: For Windows 7 or earlier versions of Windows 10 (below 1709), please continue to use ASM Manager version 1.5.9. Version 1.5.10 will not run on your system.

   If you would like to use the latest ASM Manager software, we recommend upgrading your system to the latest version of Windows 10 (at least).

Additions

1. Silver Edition bank added to Factory Packs Singles (Hydrasynth only)